EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	216	73/64.56.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 07:29
S2	0	S1 and connect and (main near4 supply) and (test $3 near4 (chamber or space)) and purg $3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 07:34
S3	26	connect and (main near4 supply) and (test$3 near4 (chamber or space)) and purg $3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 07:35
S4	0	S3 and hydrant	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 07:35
S5	4	S3 and (pressure near4 sensor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 07:37
S6	0	S5 and (purge near4 controller)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 07:38
S7	26	connect and (main near4 supply) and (test$3 near4 (chamber or space)) and purg $3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 12:11

S8	26	connect and (main near4 supply) and (test$3 near4 (chamber or space)) and purg $3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 17:45
S9	4	S8 and (pressure near4 sensor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 17:45
S10	0	connect and hydrant and (test $3 near4 (chamber or space)) and purg $3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 17:51
S11	494	connect and supply and (test$3 near4 (chamber or space)) and purg $3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 17:53
S12	0	S11 and hydrant	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 17:53
S13	21	S11 and (purge near4 controller)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 17:55
S14	0	S8 and turbidity	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:13
S15	0	S8 and (electrical near4 tester)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:16

S16	23	S8 and temperature	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:19
S17	0	S8 and (temperature near4 tester)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:19
S18	3	S8 and memory	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:31
S19	0	S8 and (data near4 download)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:34
S20	25	S8 and (power or battery)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/12/19 19:35

12/20/2008 12:07:48 AM
C:\Documents and Settings\rfrank\My Documents\EAST\Workspaces
\FluidMonitoringApparatusandMethod10595838.wsp